


Inductive - analog+ Sensors

Analog Sensor Part Number Key



Wiring Options

A) Connectorized Sensor

Bi15-M30-LIU- H1 1 4 1



B) Potted Cable

Bi 5-M18-LIU- 7M

